

2019 Ford Explorer

VIN: 1FM5K8AR9KGB23488

Damage: Paint rippling on hood. Has rear cage. Has installed push bumper.

