

Auction Vehicle No. 3

2019 Ford Explorer

VIN: 1FM5K8AR2KGB44151

Damage: Paint rippling on hood. Large crack in the windshield.

